

2430 "E" Street, N. W.  
Washington 25, D. C.  
31 July 1953

25X1A9a



re: Gasoline Pump

25X1A9a

Dear Mr. [REDACTED]:

Enclosed is bulletin of [REDACTED]  
being returned as per request in your letter of 20 July 1953.

25X1A

Proposal for the substitution of the diaphragm in lieu of the rotary type specified is rejected on the ground that it is not so efficient as the rotary type, the reasons being that more maintenance is required, the diaphragm needs periodic replacement, and the flow is less even, thus the metering is less efficient and the danger of overflow increased.

Very truly yours,



25X1A9a

Attachment

Bulletin